



TRP® TX VALVES

TRP® TX Valves are responsible for regulating air conditioning refrigerant into your trucks evaporator core to keep cabin temperatures cool.

Given the fine tolerances for effective function of the TX Valve, it is always advised that when repair of your air conditioning system is required that the receiver dryer (that removes moisture from the system) and TX valve are replaced together.

TRP® TX Valves cover all Kenworth applications and are backed by PACCAR and a national network of parts and service professionals.

You can rely on TRP® for trusted, reliable and proven replacement parts.

- ✓ **Great value alternative to OEM part**
- ✓ **Manufactured to OEM specifications**
- ✓ **12 month, unlimited kilometre warranty**


APPLICATIONS AND CROSS REFERENCES

TRP® PART NO.	DESCRIPTION	GENUINE EQUIVALENT	APPLICATION
TRP440TX	TX Valve KWAIR	329-440	Kenworth Pre 2010
TRP997TX	TX Valve KW	25188997	Kenworth 2010 – (exc. 2.1M cab Models)

FEATURES & BENEFITS

- Manufactured to OE specifications to operate in harmony with your Air Conditioning system.
- Great value alternative to OE product saving money each time a repair is required on your AC System.
- Complements existing TRP AC products including air conditioning compressors and receiver dryers, making repairs more affordable.
- 12 month, unlimited kilometre warranty standard, giving you peace of mind on the road.

COMPLEMENTARY PRODUCTS



TRP® Air Conditioning Compressors



TRP® Receiver Dryer

For further information and full warranty details visit our website

www.trpparts.com.au

Copyright ©2022 PACCAR Australia. Unauthorised reproduction in whole or part without our express written permission is strictly prohibited. Information and diagrams are provided for guidance only. PACCAR Australia reserves the right to alter product offerings and specifications at any time, without notice. PACCAR Australia makes every effort to ensure accuracy of all information but is not liable or responsible for any editorial, photographic or typographic errors. Product designs vary across different vehicle makes and models, and installed components should be identified by part number before attempting repair or replacement. Products should only be replaced by a suitably trained and qualified technician/tradesperson.

